



Photographs for Black Eagle Estates

Inspection Type: Construction-Stormwater

Photo Number: 428
Photo Date/Time: 7/22/2015
Photographer: Kacy Sable
The direction of the photo is West.

Description:

A drainage swale by the road on the south side of the subdivision. The Mandaree wastewater lagoon is shown on the far back of the photo.



Photo Number: 429
Photo Date/Time: 7/22/2015
Photographer: Kacy Sable
The direction of the photo is North.

Description:

Erosional rills observed while walking down from where photo 428 was taken. Note the lack of stabilization.





Photographs for Black Eagle Estates

Inspection Type: Construction-Stormwater

Photo Number: 431

Photo Date/Time: 7/22/2015

Photographer: Kacy Sable

The direction of the photo is West.

Description:

An overview of the northern side of the subdivision.



Photo Number: 432

Photo Date/Time: 7/22/2015

Photographer: Kacy Sable

The direction of the photo is West.

Description:

More erosional rills on the northern side of the subdivision.





Photographs for Black Eagle Estates

Inspection Type: Construction-Stormwater

Photo Number: 433
Photo Date/Time: 7/22/2015
Photographer: Kacy Sable
The direction of the photo is West.

Description:

A view at the head of the drainage swale.
Note the bent over plants and the sediment.



Photo Number: 434
Photo Date/Time: 7/22/2015
Photographer: Kacy Sable
The direction of the photo is Northeast.

Description:

More erosional rills on the northern side of the subdivision. Note the straw wattles at the banks of the drainage swale. The drainage swale runs parallel to the road on the northern side of the subdivision.





Photographs for Black Eagle Estates

Inspection Type: Construction-Stormwater

Photo Number: 435

Photo Date/Time: 7/22/2015

Photographer: Kacy Sable

The direction of the photo is West.

Description:

Another view of the drainage swale shown in photo 434.

